

Figure 13. Floodout crossing, with red mulga on shallow channels downstream; ephemeral grasses.




Figure 14. Watercourse in foreground diverted along road to a parallel watercourse

